



TPMS Application Chart - October 2023

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Acura	CSX		2008	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Acura	CSX		2012	2012		315 MHz				6-139	6-231C
Acura	ILX	DE1;DE2;DE3	2012	2015	Also known as the ILX Hybrid	315 MHz				6-139	6-231C
Acura	ILX	DE1;DE2;DE3	2016	2018		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	ILX	DE1;DE2;DE3	2019	2022		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Acura	Integra	DE4	2023	2023	Clamp-In	433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	Integra	DE4	2023	2024	Snap-In	433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Acura	MDX	YD1	2004	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Acura	MDX	YD2	2007	2013		315 MHz				6-116T	
Acura	MDX	YD3	2014	2015		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	MDX	YD3	2016	2020		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	MDX	YD8;YD9;YE1	2022	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Acura	NSX	NC1	2016	2022		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	RDX	TB1;TB2	2007	2012		315 MHz				6-116T	
Acura	RDX	TB3;TB4	2013	2015		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	RDX	TB3;TB4;TC1;TC2	2016	2019	315Mhz	315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	RDX	TC1;TC2	2019	2021	433Mhz	433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	RDX	TC1;TC2	2022	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Acura	RL	KB1	2005	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Acura	RL	KB2	2009	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Acura	RLX	KC1;KC2	2014	2015		315 MHz				6-125	
Acura	RLX	KC1;KC2	2016	2022		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	TL	UA6;UA7	2005	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Acura	TL	UA8;UA9	2009	2013		315 MHz				6-125	
Acura	TL	UA8;UA9	2014	2014		315 MHz				6-125	
Acura	TLX	UB1	2015	2017		315 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	TLX	UB;4	2018	2020		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Acura	TLX	UB5;UB6;UB7	2021	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Acura	TSX	CL9	2007	2008		315 MHz				6-116T	
Acura	TSX	CU2	2009	2014		315 MHz				6-116T	
Acura	ZDX	YB1	2010	2013		315 MHz				6-125	
Alfa Romeo	159		2006	2012		433 MHz				6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Alfa Romeo	4C	960	2013	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Alfa Romeo	8C		2007	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Alfa Romeo	Brera		2005	2010		433 MHz				6-109	6-240
Alfa Romeo	Giulia	952	2016	2022	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Alfa Romeo	Giulia	952	2017	2024	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Alfa Romeo	MiTo		2008	2012		433 MHz				6-109	6-240
Alfa Romeo	MiTo 2		2013	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Alfa Romeo	Spider		2006	2010		433 MHz				6-109	6-240
Alfa Romeo	Stelvio	949	2018	2024	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Alfa Romeo	Tonale		2023	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Aston Martin	Cygnets		2011	2013		434 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Aston Martin	DB11	AM506	2016	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	DB11	AM506	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Aston Martin	DB9	V12; VANTAGE; VOLANTE	2004	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	DBS	AM702	2007	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	DBS Superleggera	AM803	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Aston Martin	Rapide	VH400	2010	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	Rapide S	VH400	2014	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	V12 Vantage	VH800	2009	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	V12 Vantage	VH800	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	V8 Vantage	VH800	2006	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Aston Martin	V8 Vantage	VH800	2010	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	V8 Vantage	VH800	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	Vanquish	AM310	2012	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	Vanquish S	AM319	2017	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Aston Martin	Virage	AM803	2012	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	A3	8P	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	A3	8P	2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	A4	8E;B6	2002	2008	B6,B8	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	A4	8E;B7	2009	2012	B7,B8	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Audi	A5	AU484	2008	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	A6	4F;C6	2002	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	A6	4F;C6	2005	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	A6 Allroad Quattro	4B	2001	2004	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	A6 Allroad Quattro	4B	2001	2005	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	A6 Allroad Quattro	4F	2005	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	A6 Allroad Quattro	4F	2010	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	A7	4K	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	A8	4D;D2	2000	2003		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	A8	4E	2004	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	E-tron	MLB	2020	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	Q5	8R	2009	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	Q7	4L	2007	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	Q8		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	Q9		2021	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	R8	AU714;422;423	2008	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	R8	4S3;4S9	2014	2018	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS3	8VA; 8VF; 8VS; 8VM	2017	2018	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS3	8VA; 8VF; 8VS; 8VM	2017	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS4	B7;8E	2007	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS5	8F	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS6	C5;4B	2003	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	RS6	C8;5G	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS7	4GA; 4GF	2014	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Audi	RS7	4GA; 4GF	2014	2018	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RS7		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	RSQ8		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Audi	S5	AU484	2008	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	SQ5	8R	2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Audi	TT	8J	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Audi	TT RS	8S	2018	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Arnage	T;R;RL	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Azure	BY824	2006	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Bentayga	BY636	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Brooklands	BY825	2008	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Continental GT	614	2003	2005	Built Before June 2005	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Bentley	Continental GT	614	2005	2023	Built After May 2005	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Flying Spur	611	2006	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bentley	Mulsanne	BY831	2011	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	1 Series	E81;E82;E87;E88	2008	2011	Built Before October 2011	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	1 Series	E81;E82;E87;E88	2011	2013	Built After September 2011	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	2 Series	F23	2014	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	2 Series	F22;F45	2014	2020	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	2 Series	F44	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	3 Series	E46	1999	2002	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	3 Series	E46	1999	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	3 Series	E90	2007	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	3 Series	E90	2010	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	3 Series	F30; F31; F34; F80	2013	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	3 Series	F30	2014	2019	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	3 Series	G20	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	4 Series	F32	2014	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	4 Series	F32	2014	2020	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	4 Series	G22	2021	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	5 Series	E39	1997	2002		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	5 Series	E39	2003	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	5 Series	E60;E61	2006	2011	E60, E61 Only	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	5 Series	F10;F07	2011	2014	F07 Only. Built Before March 2	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
BMW	5 Series	F10;F07	2014	2016	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	5 Series	G30;G31	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	5 Series GT	G30; G31	2017	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	6 Series	E63;E64	2003	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	6 Series	F12;F13	2012	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	6 Series	F12;F13	2014	2019	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	7 Series	E38	1994	2001	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	7 Series	E38	2000	2001	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	7 Series	E66	2001	2005	E66	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	7 Series	F01;F02	2006	2011	Built before October 2011	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	7 Series	F01;F02	2011	2014	September 2010 and built before	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	7 Series	F01;F02	2014	2015	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	7 Series	G11;G12	2016	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	7 Series		2023	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	8 Series	G14;G15;G16	2017	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	Alpina B6	F13	2015	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Alpina B7	E65; E66; E67	2004	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	Alpina B7	F01; F02; F03; F04	2012	2014	Built Before May 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Alpina B7	G11; G12	2014	2023	Built After April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Alpina B8	G16	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	i Series	I01;I12	2014	2023	Built After April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	iX	I20	2022	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	M2	F22; F87	2014	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	M3	E46	2002	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M3	E46	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M3	F30	2015	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	M3	G80;G81	2019	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	M4	F32; F33; F82; F83	2015	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	M4	G82;G83	2020	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
BMW	M5	E60	2006	2010	Built before October 2010 E60	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M5	F07;F10;F11	2010	2014	September 2010 and Built before	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M5	F07;F10;F11	2014	2017	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M5	F90	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	M6	E63;E64	2006	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M6	F06; F12; F13	2012	2014	Built before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M6	F06; F12; F13	2014	2016	Built after March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	M6	F06; F12; F13	2017	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	M6	F06;F12;F13	2020	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	M7	G11	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	M8	G14; G15	2020	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	X1	E84	2013	2015	E84	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X1	F46;F48	2015	2023	F46, F48	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	X1	U11	2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BMW	X2	F39	2018	2023	F46, F48	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	X3	E83	2004	2010	E83	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X3	F25	2010	2014	F12. Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X3	F25	2014	2016	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X3	G01	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	X4	F26	2015	2018	F26	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X4	G02	2018	2023	G02	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	X5	E53	1999	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
BMW	X5	E53	2005	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X5	E70	2006	2010	E70	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X5	E70	2011	2013	Built Before September 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X5	F15	2013	2016	Built After August 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	X5	F15	2017	2019	F15	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	X5	G05	2019	2024	G05	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	X6	E71;E72	2008	2010	Built Before April 2010	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
BMW	X6	E71;E72	2010	2014	Built Between March 2010 and April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	X6	F16	2014	2019	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
BMW	X6	G06	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	X7	G07	2019	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
BMW	Z4	E85;E86;E89	2002	2010	Built before October 2010	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Z4	E89	2010	2013	Built after September 2010	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Z4	E89	2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
BMW	Z4	G29	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
BrightDrop	EV600		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
BrightDrop	Zevo 400		2024	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
BrightDrop	Zevo 600		2023	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Bugatti	Chiron		2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bugatti	Divo		2020	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Bugatti	Veyron	Grand Sport	2009	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Buick	Allure		2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Buick	Allure		2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Cascada		2016	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	Enclave		2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Buick	Enclave		2009	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Enclave		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	Enclave		2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Encore		2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Encore		2016	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	Encore GX		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Envision		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	Envision		2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	Envision		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	LaCrosse		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Buick	LaCrosse		2009	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Buick	LaCrosse		2010	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Buick	LaCrosse		2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	LaCrosse		2017	2020	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	LeSabre		2007	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Lucerne		2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Rainier		2006	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Buick	Regal		2011	2019	315 Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Regal		2018	2020	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Verano		2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Buick	Verano		2016	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	ATS	A1BL	2013	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Cadillac	ATS	A1LL	2014	2015	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	ATS	A1SL	2014	2016	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	ATS		2016	2019	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	ATS Performance		2013	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Cadillac	ATS Performance		2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	ATS Performance		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Cadillac	ATS-V		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Cadillac	CT4	A2SL	2020	2022	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Cadillac	CT4		2020	2023	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	CT5		2020	2023	Includes the CT5-V	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	CT6	O1SL	2017	2018	Import	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	CT6	A1SL	2019	2021	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	CTS	GMX322	2004	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	CTS	GMX206	2008	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	CTS	GMX226	2009	2012	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	CTS	GMX206	2012	2012	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	CTS	A1LL	2013	2013	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Cadillac	CTS	A1LL	2013	2013	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Cadillac	CTS	A1LL	2014	2015	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	CTS	A1LL	2014	2019	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	CTS	A1LL	2016	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	CTS-V		2009	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	CTS-V		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Cadillac	Deville		2001	2005		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Cadillac	DTS		2006	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	DTS		2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	ELR		2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	ELR		2016	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	Escalade	GMT926	2004	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	Escalade	GMT926	2007	2007	Built after October 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Escalade	GMT926	2007	2007	Built Before November 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Cadillac	Escalade	GMT926	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Escalade	GMT926	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Escalade	GMT926	2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Escalade	GMT926	2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	Escalade	GMT926	2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	Escalade	GMT926	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Lyriq		2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	Seville		2001	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Cadillac	SRX	GMT265	2004	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	SRX	GMT265	2007	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	SRX	GMT265	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	SRX	GMT265	2010	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	SRX	GMT265	2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	SRX	GMT265	2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Cadillac	STS	GMX295	2005	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	STS	GMX295	2009	2009	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Cadillac	STS	GMX295	2009	2011	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XLR	GMX215	2004	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Cadillac	XT4	E2UL	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XT5		2017	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XT5		2018	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XT6		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XTS		2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XTS		2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Cadillac	XTS		2017	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Avalanche		2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Avalanche		2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Avalanche		2007	2007	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Avalanche		2007	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Chevrolet	Avalanche		2008	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Aveo	G1SC	2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Aveo	G2SC	2018	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Blazer		2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Bolt EV		2017	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Bolt EV		2019	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Bolt EV		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Camaro	GMX521	2010	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Camaro	A1BC	2016	2022	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Camaro	A1BC	2016	2022	includes the Camaro ZL1 up to	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Camaro		2021	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Camaro ZL1		2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Camaro ZL1		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Caprice		2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Caprice		2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Captiva Sport	L07	2008	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Chevrolet	City Express		2015	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Chevrolet	Cobalt		2008	2010	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Cobalt		2008	2010	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Colorado	GMT355	2006	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Colorado	GMT355	2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Colorado	GMT355	2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Colorado		2021	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Colorado		2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Corvette		1997	2000		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-122	
Chevrolet	Corvette		2001	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Chevrolet	Corvette	C6	2005	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Corvette	C6	2010	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Corvette	C7	2014	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Corvette	C8	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Cruze	D1JC; D1SC; D1WC	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Cruze	J400	2016	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Cruze	J400	2019	2020	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Equinox		2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chevrolet	Equinox		2010	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Equinox	D2UC	2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Equinox	D2UC	2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Equinox		2022	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Express Series	GMT610	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chevrolet	Express Series	GMT610	2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Express Series		2012	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	G Series		2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chevrolet	HHR		2008	2009	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	HHR		2008	2010	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	HHR		2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Chevrolet	Impala		2006	2007	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Impala		2006	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Impala		2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Impala		2011	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Impala		2016	2020	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Impala		2017	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Malibu		2008	2012	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chevrolet	Malibu		2008	2012	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Malibu		2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Malibu		2016	2019	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Malibu		2016	2019	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Malibu		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Monte Carlo		2006	2007	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Monte Carlo		2006	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Orlando	J309	2012	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Silverado	GMT800	2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Silverado	GMT800	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Silverado	GMT900	2007	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Chevrolet	Silverado	GMT900;K2XX	2007	2015	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Silverado	K2XX	2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Silverado	K2XX	2018	2019	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Silverado		2019	2019	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Silverado	T1XX	2020	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Silverado	T1XX	2020	2023	1500	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Silverado	T1XX	2020	2023	DRW and SRW	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Chevrolet	Silverado	T1XX	2022	2023	LTD and HD	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Silverado	T1XX	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Sonic	T300	2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Sonic	T300	2016	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Chevrolet	Spark	M300; M1JC	2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Spark	M400	2016	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	SS		2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	SS		2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	SSR		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Suburban	GMT900	2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Suburban	GMT900	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Suburban	GMT931	2007	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Chevrolet	Suburban	GMT931	2007	2007	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Suburban		2008	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Suburban		2016	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Suburban		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Tahoe		2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Tahoe		2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Tahoe		2007	2007	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Chevrolet	Tahoe		2007	2007	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Tahoe		2008	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Tahoe	K2UC	2016	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Tahoe		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	TrailBlazer	KC; GMT360	2002	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	TrailBlazer	31UX	2021	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Traverse		2009	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Traverse		2016	2017	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Traverse		2018	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Trax	G1UC	2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Trax	G1UC	2016	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chevrolet	Uplander		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Chevrolet	Volt	D1JCI	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Volt	EV150	2016	2016	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Chevrolet	Volt		2017	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chevrolet	Volt		2019	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Chrysler	200		2011	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Chrysler	200		2015	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Chrysler	200		2017	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chrysler	300	LX	2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Chrysler	300	LX	2008	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Chrysler	300	LD	2009	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Chrysler	300	LD	2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chrysler	300		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Chrysler	300M	LX	2002	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Aspen		2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Chrysler	Concorde		2002	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Crossfire		2004	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Grand Caravan	RU	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chrysler	Intrepid		2002	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Pacifica		2004	2004	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Pacifica		2004	2005	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Pacifica		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Pacifica		2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chrysler	Prowler		1997	2001		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-103	
Chrysler	Prowler		2002	2002		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	PT Cruiser		2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Sebring	JS	2007	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Sebring	JS	2008	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Chrysler	Town and Country		2002	2003		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Town and Country		2004	2005		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Town and Country		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Chrysler	Town and Country		2008	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Chrysler	Town and Country	LX	2011	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Chrysler	Voyager	RT	2002	2003		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Chrysler	Voyager	RT	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Avenger	JS41D	2007	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Dodge	C/V		2012	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	C/V		2015	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Caliber	SE	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Caliber	SE	2011	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Dodge	Caravan		2002	2003		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Dodge	Caravan		2004	2005		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Caravan		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Challenger	LC22	2008	2021	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Challenger	LC22	2010	2016	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Challenger		2017	2021	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Challenger		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Dodge	Charger	LX	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Charger	LX	2008	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Dodge	Charger	LD	2009	2015	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Charger	LD	2009	2021	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Charger	LD	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Dodge	Dakota	ND	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Dakota	ND	2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Dart		2012	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Dodge	Durango	ND	2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Durango	ND	2009	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Durango	WD75	2011	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Durango	WK2	2016	2017	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Dodge	Durango	WK2	2016	2023	Screw-in	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Durango	SRT	2018	2023	SRT	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Dodge	Grand Caravan		2001	2003		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Dodge	Grand Caravan		2004	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Dodge	Grand Caravan		2008	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Dodge	Grand Caravan	RT	2011	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Hornet		2023	2023	Includes the GT	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Dodge	Intrepid		2002	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Dodge	Journey		2009	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Dodge	Journey	JC49	2011	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Magnum		2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Magnum		2008	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Dodge	Nitro		2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Nitro		2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	ProMaster		2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Dodge	Ram Series	DS;DJ;D2	2009	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Dodge	Ram Series	DS;DJ;D2	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Dodge	Ram Series	DS;DJ;D2	2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Dodge	Sprinter	NCV3	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Dodge	Stratus		2007	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Dodge	Viper	ZBI	2003	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Dodge	Viper	VX	2013	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Ferrari	296	F171	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	550 Maranello Evol.	F133e	2002	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	575 M-Maranello	F133	2002	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	599 GTB/GTO	F141	2004	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	612 Scaglietti	F137	2004	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	812 Superfast	F152M	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	California	F149	2009	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	Dino		2020	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	Enzo	F140	2003	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Ferrari	F12 Berlinetta	F152	2012	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	F12tdf		2015	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	F430	F131e	2004	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	F430	F131evo	2008	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	F458	F142	2010	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	F488	F142M	2015	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	F8 Tributo	F173	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	FF	F151	2011	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	FX	F140	2005	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Ferrari	GTC4Lusso T	F151M	2017	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	LaFerrari	F150	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	Portofino	F164	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Ferrari	Roma	F169	2021	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Fiat	124 Spider	CS	2017	2017		433 MHz			6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Fiat	124 Spider	CS	2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Fiat	500		2012	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fiat	500		2016	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fiat	500E		2016	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fiat	500L		2014	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fiat	500L		2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fiat	500X		2014	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Fiat	500X		2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Fisker	Karma		2012	2012		433 MHz			6-266B/6-266B-BK 6-266A-SH		
Ford	Bronco	U725	2020	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Bronco Sport	CX430	2021	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	C-Max	C344	2013	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Crown Victoria	EN114	2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	E-Series		2007	2010	Band sensor	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	E-Series		2010	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Ford	E-Series		2017	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	E-Series		2021	2023	SRW	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	E-Series		2021	2023	DRW	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	EcoSport	BK	2018	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Edge	U387	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Edge	U387	2011	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Edge	CD539;CDX706	2015	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Escape	ZB	2005	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Escape	C520	2009	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Escape		2020	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Expedition		2003	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Ford	Expedition		2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Ford	Expedition		2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Expedition		2011	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Expedition		2018	2018	Limited edition	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Expedition		2018	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Explorer	U152	2002	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Ford	Explorer	U251	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Explorer	U502	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Explorer	U502	2016	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Explorer		2020	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	F-Series		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	F-Series		2009	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	F-Series		2015	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	F-Series Super Duty		2006	2010	Built Before July 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	F-Series Super Duty		2010	2016	Built After June 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	F-Series Super Duty		2017	2023	Single Rear Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	F-Series Super Duty		2021	2022	F150 Only	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	F-Series Super Duty		2023	2023	F150/F250/F350	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Ford	Fiesta	B299	2011	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Fiesta	B479	2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Five Hundred		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Flex		2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Flex		2011	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Focus	C170	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Focus	C346	2010	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Focus RS	C346	2016	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Freestar		2004	2005		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Ford	Freestar		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Freestyle		2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Fusion		2006	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Fusion		2010	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Fusion		2017	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	GT		2017	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Mach E	CX727	2021	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Maverick		2022	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Mustang	S197	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Mustang	S197	2010	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Mustang	S197	2015	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Mustang	S197	2017	2017	lby for Gulf Cooperative Count	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Ranger		2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Ranger	P375; TKE	2019	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Shelby GT500		2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	SSV Plug in hybrid		2019	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Taurus		2007	2010	Built before June 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Ford	Taurus		2010	2013	Built After May 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Taurus		2014	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Transit	V348	2010	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Ford	Transit	V348	2019	2022	315 MHz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Transit	V348	2021	2023	433 MHz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Transit Connect	V408	2010	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Ford	Transit Connect	V408	2019	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Ford	Transit Connect	V408	2021	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Freightliner	Sprinter	NCV3	2007	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Freightliner	Sprinter	NCV3;VS30	2014	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Genesis	G70	IK	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Genesis	G80	DH	2017	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Genesis	G90	HI;RS4	2017	2022	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Genesis	G90	RS4	2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Genesis	GV60	JW	2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Genesis	GV70	JK1	2022	2025		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Genesis	GV80	JX1	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
GMC	Acadia		2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2011	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2015	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2016	2016	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2017	2017	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Acadia		2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Canyon	RG	2007	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
GMC	Canyon	RG	2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Canyon	RG	2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Canyon	RG	2018	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Canyon	RG	2020	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Canyon	RG	2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Envoy		2005	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
GMC	Hummer		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Savana		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
GMC	Savana		2010	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra		2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
GMC	Sierra		2005	2007	Schrader Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
GMC	Sierra		2007	2007	Schrader Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra		2007	2007	TRW Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
GMC	Sierra		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra	K2XG	2010	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra	K2XG	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Sierra		2018	2019	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Sierra		2019	2019	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra		2020	2023	1500	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Sierra		2022	2023	LTD and HD	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Sierra		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Terrain		2010	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Terrain		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Terrain		2018	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Yukon		2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
GMC	Yukon	GMT922	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
GMC	Yukon	GMT922	2007	2007	uilt after October 2006;Clamp	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
GMC	Yukon	GMT922	2007	2007	it before November 2006;Clamp	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
GMC	Yukon	GMT922	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Yukon	GMT922	2010	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Yukon	GMT922	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
GMC	Yukon		2016	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Yukon		2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
GMC	Yukon		2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Honda	Accord		2008	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	Civic		2008	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	CR-V	RD	2007	2011	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	CR-V	RD	2007	2011	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	CR-V	RD	2012	2014		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Honda	CR-Z	ZF1;ZF2	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	CR-Z	ZF1;ZF2	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Crosstour	TF1;TF2	2010	2015		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Honda	Element	YH1;YH2	2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Element	YH1;YH2	2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	FCX Clarity		2007	2014		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	Fit	GE	2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	Fit	GE	2009	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Fit	GK;GH;GP	2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Insight	ZE2;ZE3	2010	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Insight	ZE2;ZE3	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Odyssey	RL3;RL4	2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Odyssey	RL3;RL4	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Odyssey	RL5	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Odyssey	RL5	2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Odyssey	RL6	2018	2020		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Honda	Odyssey	RL6	2021	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Honda	Odyssey Touring	RL3;RL4	2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Odyssey Touring	RL3;RL4	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Odyssey Touring	RL5	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Odyssey Touring	RL5	2014	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Honda	Passport	YF7;YF8	2019	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Honda	Pilot	YF1;YF2	2005	2005	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Pilot	YF1;YF2	2005	2008	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Honda	Pilot	YF3;YF4	2009	2015	Alloy Wheels	315 MHz			6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	Pilot	YF3;YF4	2009	2015	Steel Wheels	315 MHz			6-266B/6-266B-BK 6-266A-SH	6-116T	
Honda	Pilot	YF5;YF6	2016	2018		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Honda	Pilot	YF5;YF6;YG1;YG2	2019	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Honda	Ridgeline	YK1	2006	2008	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Ridgeline	YK1	2006	2008	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Ridgeline	YK1	2009	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Honda	Ridgeline	YK2;YK3	2017	2020		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Honda	Ridgeline	YK3	2021	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Honda	S2000	AP2	2008	2009	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Hummer	H2		2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hummer	H3	GMT345	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Hummer	H3T	GMT345	2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Hyundai	Accent	MC	2006	2007	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Accent	MC	2006	2007	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Accent	MC;RB;RC	2008	2011	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Accent	RB;RC	2012	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Accent	RB;RC	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Accent	HC	2015	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Azera	TG	2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Azera	HG	2012	2013		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Azera	HG;IG	2014	2017		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Elantra	HD	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Elantra	MD;UD	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Elantra	MD; HD	2014	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Elantra	AD	2017	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Elantra	CN7	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Elantra GT	MD; HD	2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Elantra GT	MD; HD	2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Hyundai	Elantra GT	AD	2018	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Elantra N	CN7	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Elantra Touring	HD;MD;UD	2009	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Hyundai	Entourage	VQ	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Equus	VI	2011	2013	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Equus	VI	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Equus	VI	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Genesis	BH;DH	2009	2014	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Genesis	BH	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Genesis	DH; BK	2013	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Genesis	DH; BK	2015	2016	Sedan	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Ioniq	AE	2016	2023	Includes 5	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Ioniq 5		2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Kona	OS;SX2	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Nexo	FE	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Hyundai	Palisade	LX2	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Hyundai	Santa Cruz		2022	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Santa Fe	CM	2006	2008	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Santa Fe	CM	2008	2009	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Santa Fe	CM	2010	2012	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Hyundai	Santa Fe	DM	2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Santa Fe	DM	2015	2019	XL for 2019	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Santa Fe	TM	2019	2023	Non XL	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Hyundai	Sonata	NF	2006	2008	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Sonata	YF	2009	2010	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Sonata	YF	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Sonata	YF	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Sonata	YF	2015	2016	Non-Hybrid	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Sonata	YF	2015	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Hyundai	Sonata	YF	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Tiburon	GK	2007	2008	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Tucson	JM;LM	2006	2010	ne and built before November	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Tucson	JM;LM	2006	2010	ne and built before November	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Hyundai	Tucson	LM	2010	2013	Built After October 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Tucson	LM	2014	2015	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Hyundai	Tucson	TLE	2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Hyundai	Tucson	NX4	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Veloster	FS	2011	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Hyundai	Veloster	JS	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Venue	QX1	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Hyundai	Veracruz	EN	2006	2008	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Hyundai	Veracruz	EN	2008	2012	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Infiniti	EX	P53B	2008	2010	Built before April 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	EX	P53B	2010	2014	Built after March 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	FX	S50	2003	2007	Built Before August 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	FX	S51	2007	2008	Built After July 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	FX	P53C	2009	2010	Built Before April 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	FX	P53C	2010	2014	Built After March 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	G	V35	2003	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	G	L53A	2007	2007	Sedan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	G	L53A	2007	2007	Coupe	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	G	L53A	2008	2010	Built before April 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	G	L53A	2010	2013	Built After March 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	JX35	L50	2013	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Infiniti	M	Y34;Y50	2003	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	M	Y50	2008	2008	Built After August 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	M	Y50	2009	2010	Built After July 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	M	Y51	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Infiniti	Q40	V36	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	Q45	F50	2003	2006	Built Before September 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	Q45	F50	2006	2006	Built After August 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	Q50	V37	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Infiniti	Q50	D53H	2016	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Infiniti	Q60	V36	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	Q60	V37	2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Infiniti	Q70	Y51	2014	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX30	H15	2017	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Infiniti	QX4 / SUV	R50	2003	2003		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	QX50	J50;J55	2013	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX50	J55	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Infiniti	QX55	J55	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Infiniti	QX56	JA60	2004	2006	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	QX56	JA60	2005	2006	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	QX56	JA60	2007	2007	Built Before May 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	QX56	JA60	2007	2010	Built After April 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Infiniti	QX56	Z62	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX60	D53H	2014	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Infiniti	QX60	L51	2022	2023		433 MHz			6-266B/6-266B-BK 6-266A-SH		6-207
Infiniti	QX70	P53C	2014	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX80	Z62	2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX80	Z62	2017	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Infiniti	QX80	Z62	2018	2023	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Isuzu	Ascender		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Isuzu	i-290		2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Isuzu	i-370		2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Isuzu	Rodeo	UES73FW	2004	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Jaguar	E-Pace	X540	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Jaguar	F-Pace	X761	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	F-Type	X152	2014	2014	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	F-Type	X152	2014	2016	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	F-Type	X152	2015	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	I-Pace		2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	S-Type		2005	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	S-Type		2007	2008	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	Super V8	X350	2005	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	Super V8	X350	2005	2006	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	Super V8	X350	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	Super V8	X350	2007	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	Vanden Plas	XJ	2004	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	Vanden Plas	XJ	2004	2006	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	Vanden Plas	XJ	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	Vanden Plas	XJ	2007	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	X-Type	CF1	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	X-Type	CF1	2007	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XE	X760	2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	XF	X250	2009	2016	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XF	X250	2009	2018	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XF	X250	2017	2022	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	XFR	X250	2010	2015	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XFR	X250	2010	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XFR-S	X250	2013	2015	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XFR-S	X250	2013	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XJ	X350	2005	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XJ	X350	2005	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XJ	X351	2010	2011	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XJ	X351	2010	2011	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Jaguar	XJ	X351	2012	2021	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XJ	X351	2015	2021	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jaguar	XK	X150	2005	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XK	X150	2005	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XK	X150	2010	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XK	X150	2010	2012	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jaguar	XK	X150	2011	2012	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XK	X150	2013	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jaguar	XK	X150	2013	2015	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Jeep	Cherokee	KL	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Jeep	Cherokee	KL	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1 / 6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Jeep	Commander	XK	2006	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jeep	Commander	XK	2007	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jeep	Commander	XK	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Commander	XK	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Compass	MK49	2007	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jeep	Compass	MK49	2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Compass	MP	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Gladiator	JT	2020	2021	Before July 2021	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Jeep	Gladiator	JT	2021	2023	After June 2021	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Cherokee	WJ; WG	2001	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Jeep	Grand Cherokee	WH	2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jeep	Grand Cherokee	WK	2008	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Cherokee	WK	2009	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Cherokee	WK; WK2	2011	2014	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Cherokee	WK; WK2	2012	2015	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Grand Cherokee	WK; WK2	2015	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Cherokee	WK; WK2	2016	2017	Snap-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Jeep	Grand Cherokee	WK; WK2	2016	2022	Screw in	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Jeep	Grand Cherokee	SRT	2016	2022	Clamp-In	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Jeep	Grand Cherokee	WL	2021	2027		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Grand Wagoneer	WL	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Liberty	KJ	2002	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Jeep	Liberty	KJ	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Liberty	KJ	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Liberty	KK	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Liberty	KK	2009	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Liberty	KK	2011	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Patriot	MK74	2007	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Jeep	Patriot	MK74	2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Patriot	MK74	2018	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Renegade	BU	2015	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Jeep	Renegade	BU	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wagoneer	WS	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wrangler	JK	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Wrangler	JK	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wrangler	JK	2009	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Jeep	Wrangler	JK	2011	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wrangler	JK	2013	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wrangler	JL	2015	2021	Built Before July 2021	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Jeep	Wrangler	JL	2022	2028	Built After June 2021	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Kia	Amanti		2007	2009	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Kia	Amanti		2010	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Borrego	HM	2009	2011	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Cadenza	VG	2014	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Cadenza	YG	2017	2021	433Mhz- Limited Edition	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Carnival	KA4	2022	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Kia	EV6	CV	2022	2023		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Kia	Forte	TD;YD	2010	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Forte	YD	2014	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Forte	BD	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Kia	K5	DL3	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	K900	KH	2015	2017		433 MHz			6-266B/6-266B-BK 6-266A-SH		6-207
Kia	K900	RJ	2018	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Kia	Magentis	TF	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Niro	DE	2017	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Niro	SG2	2021	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Optima	MG	2006	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Optima	TF	2011	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Optima	TF	2013	2016	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Optima	JF	2016	2022	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Rio	UB	2007	2011	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Rio	UB	2012	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Rio	YB	2018	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Rondo	UN	2007	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Sedona	VQ	2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Sedona	VQ	2009	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Kia	Sedona	YP	2015	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Kia	Seltos	SP2	2021	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Kia	Sorento	XM	2007	2010	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Kia	Sorento	XM	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Sorento	UM	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Sorento	UM	2016	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Sorento	UM	2018	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Sorento	MQ4	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Kia	Soul	AM	2010	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Soul	PS	2014	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Kia	Spectra		2006	2009	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Sportage	JE;KM	2005	2008	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Kia	Sportage	JE;KM;SL	2009	2013	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Sportage	SL;QL	2014	2016	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Kia	Sportage	QL; SL	2016	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Kia	Stinger	CK	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Kia	Telluride		2020	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lamborghini	Aventador	LP700;4	2012	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	Gallardo	LP560;LP570LP;550	2008	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	Huracan	LP6104	2014	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	Murcielago	LP640; LP670	2006	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	One Off		2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	Reventon		2007	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Lamborghini	Urus		2018	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Land Rover	Defender	DC110	2015	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Defender	L663	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Discovery	LR	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Discovery Sport	LC	2015	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	LR2	L319	2008	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Land Rover	LR2	L319	2008	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	LR2	L319	2015	2015	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	LR3	L318	2002	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Land Rover	LR3	L319	2006	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Land Rover	LR3	L319	2006	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	LR4	L319	2010	2011	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Land Rover	LR4	L319	2010	2011	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	LR4	L319	2012	2014	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	LR4	L319	2015	2016	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Range Rover	LM	2002	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Land Rover	Range Rover	LM	2006	2011	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Land Rover	Range Rover	LM	2006	2011	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover	LG	2012	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover	LG	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover	LG	2015	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Range Rover Evoque	LV	2011	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Evoque	LV	2015	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Evoque	LV	2015	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Range Rover Sport	LS	2006	2011	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Land Rover	Range Rover Sport	LS	2006	2011	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Sport	LS	2012	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Sport	LS	2014	2014	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Range Rover Sport	LG	2014	2014	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Sport	LG	2015	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Land Rover	Range Rover Sport	LG	2015	2022	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Land Rover	Range Rover Velar	LY	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Lexus	CT	080A	2011	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	ES	XV40	2007	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	ES	XV60	2013	2018	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	ES	XZ10	2018	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GS	620N	2005	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GS	920L	2013	2021	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GX	837L	2004	2006	Built Before March 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GX	J120;J150	2006	2017	February 2006 and before Sept	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GX	837L	2017	2019	Built after August 2017	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	GX	J150	2020	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	HS	ANF10	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	IS	XE20	2006	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	IS	XE30	2014	2014	IS F Only	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Lexus	IS	XE30	2014	2020	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	IS	XE30	2021	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LC	XZ100	2017	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LC	XZ100	2018	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LFA	LFA10	2012	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LS	200; PRADO	2007	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LS	XF40	2013	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LS	200; PRADO	2018	2022	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LS	200; PRADO	2018	2022	Highline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LX	J200	2005	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	LX	J200	2016	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	NX	AZ10	2015	2021	Lowline	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	NX	AZ20	2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	RC	GSC10; USC10	2015	2020	lowline. Also known as the RC F	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	RC	XC10;USC10	2021	2022	Also known as the RC F	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	RX	XU30	2006	2015	Made in USA	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	RX	AL10	2006	2015	Made in Japan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	RX	AL20	2016	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	SC	Z40	2002	2006		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	SC	Z40	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lexus	UX	ZA10	2019	2024		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Lincoln	Aviator	UN152	2003	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Lincoln	Aviator	U611	2020	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	Continental		2017	2020	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	Continental		2017	2020	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	Corsair		2020	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	Mark LT		2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	MKC		2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKC		2018	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Lincoln	MKS		2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	MKS		2011	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKT		2010	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	MKT		2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKT		2016	2020	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKX	U388	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	MKX	U388	2011	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKX	U540	2016	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	MKX	U540	2016	2021	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	MKZ	MY	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	MKZ	MY	2010	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	MKZ	MY	2017	2017	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	MKZ	MY	2017	2021	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	Nautilus	MKX	2019	2024	Limited edition	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	Navigator	U222	2003	2004		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Lincoln	Navigator	U222	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Lincoln	Navigator	U418	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	Navigator	U418	2011	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Lincoln	Navigator	U554	2018	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Lincoln	Town Car	FN145	2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lincoln	Zephyr	MY	2006	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Lotus	3 Eleven		2016	2022		433 MHz			6-266B/6-266B-BK 6-266A-SH		
Lotus	Elise	Monza	2008	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Lotus	Evora	Eagle	2010	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Lotus	Evora	Facelift	2015	2022		433 MHz			6-266B/6-266B-BK 6-266A-SH		
Lotus	Exige	Monza	2008	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Lotus	Exige		2016	2022		433 MHz			6-266B/6-266B-BK 6-266A-SH		
Maserati	Coupe	M145	2002	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Maserati	Ghibli	M157	2014	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Maserati	Gran Cabrio	M147	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Gran Sport	M147	2005	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Gran Turismo	M145	2008	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Gran Turismo	M145	2013	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Gran Turismo	M145	2014	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Maserati	Grecale		2022	2023		433 MHz			6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Maserati	Levante	WM	2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Maserati	Quattroporte	M139	2004	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Maserati	Quattroporte	M139	2010	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Quattroporte	M139	2013	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Maserati	Quattroporte	M139	2014	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Maserati	Spyder		2002	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mazda	2	J64F; J03	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	2	DJ;DL	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	3	BL	2004	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	3	BP	2019	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	5	CW	2006	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	6	GH	2005	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	6	GJ; GL	2019	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	B Series	J26E; CD; UN	2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mazda	CX-3		2019	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-30	DM	2020	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	CX-5	J53C;KF	2017	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-50		2023	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	CX-7	J31; ER	2007	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-9		2007	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-9	TB	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-9	TB	2015	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	CX-9	TB	2018	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mazda	CX-9	TC	2020	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	MX-30	DR	2022	2022	CA Only	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	MX-5	J04C; NC	2006	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	MX-5	J04C; NC	2009	2014	With Run Flats	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	MX-5	J04C; NC	2011	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	MX-5	J04C; NC	2021	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mazda	RX-8	SE3P	2004	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mazda	Tribute		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mazda	Tribute		2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
McLaren	570		2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	600LT		2019	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	650S	Coupe; Spider	2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	675LT		2016	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	720S		2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	Artura		2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	MP4-12C	12C	2012	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
McLaren	P1	S;GTRS	2013	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mercedes	A-Class	W247	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	AMG GT	190	2016	2021	190	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	AMG GT	290	2019	2022	4 Door 290	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	B-Class	W246; W242; W247	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	B-Class	W247	2019	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	C-Class	W204; S204	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	C-Class	W204; S204	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	C-Class	W204; S204	2011	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	C-Class	W204; S204	2014	2014	Built Before December 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	C-Class	205	2014	2021	Built After December 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	C-Class	206	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	CL-Class	C215	2000	2006		433Mhz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mercedes	CL-Class	C215	2001	2007	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	CL-Class	550;600	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	CL-Class	550;600	2007	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	CL-Class	600	2010	2010	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CL-Class	600	2011	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CL-Class	550	2014	2014	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLA-Class	X117; X118	2014	2014	Built Before February 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLA-Class	X117; X118	2014	2022	Built After January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	CLK-Class	55;63	2006	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLS-Class	55;63;500;550	2005	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	CLS-Class	55;63;500;550	2006	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	CLS-Class	55;63;500;550	2006	2011	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	CLS-Class	550	2012	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLS-Class	550	2014	2014	Built Before February 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLS-Class	559	2014	2015	Built After January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	CLS-Class	550	2016	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	CLS-Class	C257	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	E-Class	W210; W211	2000	2005		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	E-Class	W211	2006	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	E-Class	550	2006	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	E-Class	350	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	E-Class	500	2011	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	E-Class	W213	2014	2014	Built Before February 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	E-Class	W213	2014	2017	Built After January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	E-Class	W213	2018	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	EQC	N293	2021	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	EQC	N293	2023	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	EQS	V297	2022	2024		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	G-Class	500	2007	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mercedes	G-Class	W463	2008	2015	Built Before February 2015	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	G-Class	W463	2015	2018	Built After January 2015	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	G-Class	W464	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GL-Class	320	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	GL-Class	350	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GL-Class	350	2011	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GL-Class	450	2014	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GL-Class	450	2014	2020	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLA-Class	X156	2015	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLA-Class	H247	2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	GLB-Class	X247	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	GLC-Class	X253; C253	2016	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLE-Class	C292;	2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLE-Class	C167	2019	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	GLK-Class	X204	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GLK-Class	X204	2011	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GLK-Class	X204	2014	2014	Built Before January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	GLK-Class	X204	2014	2017	Built After December 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLS-Class	X166	2017	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	GLS-Class	X167	2020	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Mercedes	M-Class	W164	2006	2008	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	M-Class	W164	2006	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	M-Class	W164	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	M-Class	W164	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	M-Class	W166	2011	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	M-Class	W166	2014	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	M-Class	W166	2015	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	Maybach S600	W222	2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	Metris	W447	2016	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mercedes	R-Class	W251; V251	2006	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	R-Class	320	2006	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	R-Class	320	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	R-Class	350	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	R-Class	350	2011	2012	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	S-Class	W220	2000	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	S-Class	W220	2000	2006	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	S-Class	550	2007	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	S-Class	550	2007	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	S-Class	550	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	S-Class	550	2014	2014	Built Before February 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	S-Class	550	2014	2022	Built After January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	S-Class	W222; X222; V222	2020	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	S-Class	223	2021	2023	Sedan	433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	SL-Class	600	2000	2005	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	SL-Class	R230	2000	2005	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	SL-Class	550	2006	2012	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	SL-Class	550	2006	2012	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	SL-Class	63	2013	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SL-Class	R231	2014	2014	Built Before January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SL-Class	R231	2014	2020	Built After December 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	SL63		2022	2022		433 MHz	PREM-NFC	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	SLC-Class	R172	2017	2020		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	SLK-Class	300	2008	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SLK-Class	350	2012	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SLK-Class	350	2014	2014	Built Before January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SLK-Class	350	2014	2019	Built After December 2013	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	SLR-Class	R199	2001	2005	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	SLR-Class	199	2001	2007	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mercedes	SLR-Class	R199	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Mercedes	SLR-Class	R199	2008	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	SLR-Class	R199	2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	SLS-Class	C197; A197	2011	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SLS-Class	C197; A197	2014	2014	Built Before February 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	SLS-Class	C197; A197	2014	2015	Built After January 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercedes	Sprinter	906	2007	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-206B
Mercedes	Sprinter	906	2010	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-218
Mercedes	Sprinter	FR	2014	2018	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mercedes	Sprinter	VS30	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Mercury	Grand Marquis		2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Mariner		2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Mariner		2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mercury	Milan		2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Milan		2010	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mercury	Montego	D333	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Monterey		2004	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Mercury	Monterey		2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Mountaineer		2002	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Mercury	Mountaineer		2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mercury	Sable		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Mini	Cabrio	R52	2007	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Cabrio	R57	2010	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Cabrio	R57	2014	2022	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Clubman	R55	2007	2009	Built Before October 2009	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Clubman	R55	2009	2014	September 2009 and Built Before	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Clubman	F54	2014	2024	Built After July 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mini	Cooper	R56	2007	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Cooper	R56	2010	2015	R56	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mini	Cooper	F55	2015	2024	F55	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mini	Countryman	R60	2010	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Countryman	R60	2014	2022	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Coupe	R58	2012	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Coupe	R58	2014	2015	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Paceman	R61	2013	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Paceman	R61	2014	2016	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Roadster	R59	2012	2014	Built Before April 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mini	Roadster	R59	2014	2015	Built After March 2014	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Mitsubishi	Eclipse	DK2A;DK4A	2006	2007	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Eclipse	DK2A;DK4A	2006	2009	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Eclipse	DK2A;DK4A	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Eclipse Cross	GK1W;GL3W	2018	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Mitsubishi	Endeavor		2004	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Mitsubishi	Endeavor		2006	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Endeavor		2010	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Galant		2004	2006		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Mitsubishi	Galant		2007	2009	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Galant		2007	2012	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Galant		2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	i-MIEV		2012	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	i-MIEV		2013	2018		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Mitsubishi	L200		2014	2022		433 MHz			6-266B/6-266B-BK 6-266A-SH		6-208
Mitsubishi	Lancer	GS41	2008	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	Mirage	Aoo;LA;A10	2014	2020	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Mitsubishi	Mirage	Aoo;LA;A10	2014	2023	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	Montero	V6o;NM;NP	2003	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Mitsubishi	Outlander	V6o;NM;NP	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	Outlander	RE	2008	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Mitsubishi	Outlander	GM;GN;ZM	2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Mitsubishi	Outlander Sport	V6o;NM;NP	2013	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Mitsubishi	Outlander Sport	RE	2014	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	Outlander Sport		2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Mitsubishi	Raider		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Mitsubishi	RVR	GA;XA;XB;XC;XD	2011	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Mitsubishi	RVR	GA;XA;XB;XC;XD	2018	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	350Z	Z33	2003	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	350Z	Z33	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	370Z	C53D	2009	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	370Z	C53D	2010	2010	Built Before July 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	370Z	C53D	2010	2021	Built After June 2010	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Altima	L32	2007	2013	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Altima	L32	2012	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Altima	L33	2013	2014	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Altima	L33	2015	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Altima	L34	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Ariya	FE0	2022	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Nissan	Armada	TA60	2004	2008	Alloy Wheels, SE	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Armada	TA60	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Armada	TA60	2008	2013	LE	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Armada	TA60	2014	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Armada	Y62	2017	2017	Built Before June 2017	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Armada	Y62	2017	2018	Built After May 2017/433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Armada	Y62	2018	2023	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Cube	X12B	2009	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Cube	X12B	2011	2013	Krom, SL	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Cube	X12B	2013	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Cube Ikey	X12B	2011	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Nissan	Frontier	D40	2003	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Frontier	D40	2005	2008	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Frontier	D40	2005	2008	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Frontier	D40	2009	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Frontier	D40	2014	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Frontier	D40	2016	2021	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Frontier		2020	2021	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Nissan	Frontier		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	GT-R	D52E	2009	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	GT-R	D52E	2014	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	GT-R	D52E	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	GT-R	D52E	2017	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Juke	F15	2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Juke	F15	2012	2012	With I-Key; Built between 07/11-09	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Juke	F15	2012	2015	With I-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Juke	F15	2012	2015	Without I-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Juke	F15	2016	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Juke Ikey	F15	2011	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Kicks	P15	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Nissan	Leaf	ZEo;AZEo	2011	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Leaf	ZEo;AZEo	2013	2014	Built after December 2012	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Leaf	B12G	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Leaf	B12G	2017	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Leaf	B12G	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Maxima	A34	2006	2007	Built Before May 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Maxima	A34;A35	2007	2010	Built After April 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Maxima	A35	2011	2012	Built before May 2012	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Maxima	A35	2012	2015	Built after April 2012	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Maxima	A36	2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Nissan	Maxima	A36	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Nissan	Micra	K14	2017	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Murano	Z50	2003	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Murano	P42D	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Murano	P42D	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Murano	P42D	2011	2014	Built after November 2011	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Murano	Z51	2015	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Murano	Z51;P42M	2019	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-505
Nissan	NV Series	H60; D23	2012	2021	1500;2500;3500	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	NV-200	H60; D23	2013	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Pathfinder	R51	2003	2003		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Pathfinder	R51	2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Pathfinder	R51	2004	2006	Built Before April 2004	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Pathfinder	R51	2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Pathfinder	R51	2011	2012	Schrader Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Pathfinder	R51	2012	2012	Continental	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Pathfinder	R51; R52	2013	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Pathfinder	R53	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Qashqai	J11	2017	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Quest	V42	2004	2006	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Quest	V42	2005	2007	Built before January 2007	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Quest	V42	2007	2009	Built after December 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Quest	RE52	2011	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Quest	RE52	2017	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Rogue	J10;NJ10	2008	2012	Built before July 2012	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Rogue	J11	2012	2013	Built before June 2012	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Rogue	J11	2014	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Rogue	J11	2017	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Rogue	J11	2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Nissan	Rogue Select	J11	2014	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Rogue Sport	J11	2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Sentra	B16	2007	2008	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Sentra	B16	2007	2010	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Sentra	B16	2011	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Sentra	L12F; B17	2013	2016	Without I-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Sentra	L12F; B17	2013	2016	With I-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Sentra	L12F; B17	2017	2019	With I-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Sentra	L12F; B17	2017	2022	Without I-Key	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Nissan	Sentra	L12F; B17	2020	2023	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Titan	A60	2004	2005	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Titan	A60	2004	2007	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Titan	A60	2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Titan	A60	2011	2015	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Titan	A60	2014	2015	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Titan	A61	2016	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Titan	A61	2017	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Nissan	Versa	C11	2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Versa	C11	2012	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Versa	C11;N17	2012	2019	SL	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Versa	N17	2013	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Versa	N18	2020	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Nissan	Versa Note	E12	2014	2021	SL	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Nissan	Versa Note	E12	2014	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Nissan	Xterra	WD22	2003	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Xterra	N50	2005	2006	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Xterra	N50	2006	2006	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Xterra	N50	2007	2013	Built Before November 2013	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-103	
Nissan	Xterra	N50	2013	2015	Built after October 2013	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Nissan	Xtrail		2021	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Nissan	Z	RZ34	2023	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Plymouth	Prowler		2002	2002		315 MHz			6-266B/6-266B-BK 6-266A-SH	6-103	
Pontiac	G3	T250	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Pontiac	G5		2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Pontiac	G5		2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Pontiac	G6		2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Pontiac	G6		2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Pontiac	G8	GMX557	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Pontiac	Grand Prix		2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Pontiac	Montana-SV6		2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	
Pontiac	Solstice		2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Pontiac	Torrent		2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Pontiac	Vibe		2008	2010	Made in Japan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Pontiac	Vibe		2008	2010	Made in USA	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Pontiac	Wave	G3	2007	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Porsche	718 Boxster	GTS	2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	911	997	2005	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	911	997	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	911	997	2010	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	911	991	2012	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	911	991	2012	2016	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	911	GT3	2017	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	911	992	2018	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	918 Spyder		2015	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	997 GT3	CUP;R;RSR	2007	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	997 GT3	CUP;R;RSR	2010	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Boxster	987;2	2005	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	Boxster	987;2	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Porsche	Boxster	987;2	2010	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Boxster	981	2013	2015	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Boxster	981	2013	2016	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Boxster	982	2017	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Boxster	982	2018	2020	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Carerra GT	987	2004	2005		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	Cayenne	955;9PA	2002	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	Cayenne	955;9PA	2003	2006	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	Cayenne	955;9PA1	2008	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayenne	955;9PA1	2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayenne	955;9PA1	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayenne	955;92A	2011	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayenne	955;92A	2015	2024	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayenne	9Y3	2017	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayman	987C	2005	2008		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Porsche	Cayman	987C2	2009	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayman	981	2014	2015	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayman	981	2014	2016	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayman	982	2017	2022	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Cayman	982	2018	2023	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Macan	95B	2015	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Macan	95B	2018	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Panamera	970	2010	2013	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Panamera	970	2010	2013	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Panamera	970	2014	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Panamera	G2	2018	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Taycan	J1	2020	2022	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Porsche	Taycan	J1	2020	2023	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
RAM	1500	DR;DH;D1;DC;DM	2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
RAM	1500	DS;DJ;D2	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	1500	DS;DJ;D2	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	1500	DS;DJ;D2	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	1500	DT	2019	2023	DT (6-lug)	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	1500	DS;DX	2019	2023	DS/DX (5-lug)	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	2500/3500	DR;DH;D1;DC;DM	2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
RAM	2500/3500	DS;DJ;D2	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	2500/3500	DS;DJ;D2	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	2500/3500	DS;DJ;D2	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	2500/3500	DT	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	3500 Dually	DR;DH;D1;DC;DM	2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
RAM	3500 Dually	DS;DJ;D2	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	3500 Dually	DS;DJ;D2	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	3500 Dually	DS;DJ;D2	2014	2018	Steel wheel outer sensor	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	3500 Dually	DS;DJ;D2;DT	2014	2021	Alloy wheel outer sensor	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
RAM	3500 Dually	DS;DJ;D2;DT	2014	2023	2 rear inner wheels	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	3500 Dually	DS;DJ;D2;DT	2019	2023	Steel wheel outer sensor	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	4500	DR;DH;D1;DC;DM	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
RAM	4500	DS;DJ;D2	2009	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	4500	DS;DJ;D2	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	4500	DT	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	5500	DR;DH;D1;DC;DM	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
RAM	5500	DS;DJ;D2	2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	5500	DS;DJ;D2	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	5500	DS;DJ;D2	2014	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	5500	DT	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
RAM	ProMaster		2014	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
RAM	ProMaster		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	ProMaster City		2015	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
RAM	Truck		2008	2009	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
RAM	Truck		2009	2009	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	Truck		2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
RAM	Truck		2014	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Renault	Koleos		2019	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-208
Rivian	EDV 500		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rivian	EDV 700		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rivian	R1S		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rivian	R1T		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rivian	RCV		2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rivian	RPV		2021	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		
Rolls Royce	Black Badge		2019	2019		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Cullinan		2020	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Rolls Royce	Dawn	RR06	2016	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Drophead Coupe	RR02	2009	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Ghost	RR04	2009	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Ghost	RR04	2016	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Phantom	RR01	2007	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Phantom	RR01	2012	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Phantom	RR01	2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-235
Rolls Royce	Wraith	RR05	2014	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Rolls Royce	Wraith	RR05	2016	2016		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Saab	9-3	YS3F	2004	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Saab	9-3	YS3F	2008	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Saab	9-4X		2011	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Saab	9-5	YS3G	2004	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Saab	9-5	YS3G	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Saab	9-May	YS3G	2010	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Saab	9-7X		2005	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-102	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Saturn	Astra	I	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Saturn	Aura	XE;XR	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Saturn	Aura	XE;XR	2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Saturn	Outlook		2007	2008	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Saturn	Outlook		2008	2010	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Saturn	Sky		2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Saturn	Vue		2007	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Scion	FR-S	ZN6;ZC6	2013	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Scion	iM		2016	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Scion	iQ	AJ10	2012	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Scion	tC	AT10;AT20	2006	2016	Built before June 2006	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Scion	xB	E150	2008	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Scion	xD	XP110	2008	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Smart	Fortwo	W451	2008	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-120	6-228T
Smart	Fortwo	A453	2015	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Ascent	TR8	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	B9 Tribeca	B9; 00X	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Subaru	BRZ	E88	2013	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Subaru	BRZ		2022	2023		315 Mhz			6-266B/6-266B-BK 6-266A-SH		
Subaru	Crosstrek	GP	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Crosstrek	GT	2018	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Forester	SJ	2008	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Forester	FMS	2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Forester	SK	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Impreza	GE;GV;GH;GR	2008	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Impreza	MF1	2015	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Impreza	HR3	2017	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Legacy	BL;BP	2004	2008	Clamp-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Subaru	Legacy	BM;BR	2008	2009	Snap-In	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Subaru	Legacy	BM;BR	2010	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Legacy	EZ5;04AL	2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Legacy	GC7	2018	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Outback	B4F	2004	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-104	
Subaru	Outback	EZ5	2008	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Outback	04AL	2015	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	Outback	HR3	2018	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	Soltera	EA10	2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Subaru	Tribeca	B9; 00X	2008	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	WRX	GE;GV;GH;GR	2009	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	WRX	VL9	2015	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	WRX	HR3	2022	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Subaru	WRX STI	GE;GV;GH;GR	2009	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	WRX STI	VL9	2016	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	XV Crosstrek	MF1	2013	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Subaru	XV Crosstrek	HQ4	2017	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Suzuki	Equator		2009	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Suzuki	Forenza	J200;J300	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Suzuki	Grand Vitara	JT	2005	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Suzuki	Kizashi		2010	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Suzuki	Reno	J200;J300	2007	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Suzuki	SX4	GY;EY;RW	2007	2013		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Suzuki	Verona	V200	2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Suzuki	XL-7		2005	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Suzuki	XL-7		2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-108	6-201
Tesla	Model 3		2017	2020	Built Before October 2020	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Tesla	Model 3		2020	2023	Built After September 2020	BLE			6-284-BK / 6-284-BS		6-284-BK
Tesla	Model S		2012	2014	Baolong	433 MHz			6-266B/6-266B-BK 6-266A-SH		
Tesla	Model S		2014	2021	Built Before June 2021	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Tesla	Model S		2021	2023	Built After May 2021	BLE			6-284-BK / 6-284-BS		6-284-BK

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Toyota	Highlander	XU40	2007	2013	Made in USA. Includes the Highlander	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Highlander	440A	2014	2019	Smart-Key. Includes the Highlander	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Highlander	440A	2014	2019	Model made in Canada. Includes the Highlander	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Highlander	XU40	2020	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Toyota	Highlander Hybrid		2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Toyota	Land Cruiser	J100	2005	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Land Cruiser	J200	2008	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Land Cruiser	J200	2016	2021		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Matrix	E14	2007	2011	Made in USA	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Matrix	E14	2007	2011	Made in Japan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Matrix	E140	2012	2014		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Mirai	JPD1	2016	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius	W3	2006	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius	W5; 590L	2013	2015		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius	W5; 590L	2016	2019	Highline. Also known as the Prius Prime	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius	W5; 590L	2019	2022	Highline. Also known as the Prius Prime.	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius	W5; 590L	2022	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius C	NHP10	2012	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius V	XW30;XW50	2012	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Prius V	XW50	2017	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	A3	2006	2012	Made in Japan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	410A; A4	2009	2013	Made in Canada	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	410A; A4	2013	2013	Made in Japan	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	410A; A4	2013	2018	Made in Canada and W/O Smart-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	RAV4	410A; A4	2014	2018	Made in Canada and with Smart-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	410A; A4	2019	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	RAV4	XA50	2019	2022	Made in Canada and W/O Smart-Key	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Toyota	Sequoia	XK30;XK40	2004	2007	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Sequoia	XK30;XK40	2004	2007	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Toyota	Sequoia	XK60	2008	2013	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sequoia	XK60	2008	2013	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sequoia	XK60	2014	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sequoia	XK60	2018	2020	TRW	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Toyota	Sequoia	XK60	2020	2021	Pacific	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Sequoia	XK80	2022	2023		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Sienna	XL20;XL30	2006	2013	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sienna	XL20;XL30	2006	2013	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sienna	XL30	2014	2020		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Sienna	XL40	2021	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-211
Toyota	Solara	XV30	2006	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Supra	J29;DB	2019	2026	Built After April 2019. Also known as the GR Supra.	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-240
Toyota	Tacoma	N220	2005	2006	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tacoma	N240	2005	2006	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tacoma	N250	2007	2015	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tacoma	N260	2007	2015	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tacoma	N270	2016	2021	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tacoma	N270	2016	2023	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tundra	XK30;XK40	2005	2006	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tundra	XK30;XK40	2005	2006	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tundra	XK50	2007	2011	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Tundra	XK50	2007	2011	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Tundra	XK50	2012	2015	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Tundra	XK50	2012	2017	Steel Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	
Toyota	Tundra	XK50	2017	2017		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tundra	XK50	2018	2022	Steel Wheels	315 MHz			6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Tundra	XK50	2018	2022	Alloy Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-125	6-236
Toyota	Venza	AV10	2009	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Venza	XU80	2021	2022		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Toyota	Yaris	XP150	2007	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Yaris	P13; 400B	2012	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Toyota	Yaris	XPA1F	2013	2019		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-116T	
Volkswagen	Arteon	VW483	2019	2023		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	Atlas		2023	2024		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	Beetle	VW314	2008	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	CC	VW358	2009	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	CC	VW358	2012	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	CC	VW464	2014	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	CC	VW464	2015	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	EOS		2007	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Golf	1K;5K	2006	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Golf	R32	2008	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	GTI	1K	2006	2007	18" Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	GTI	1K	2006	2012		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Jetta	5C6	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Passat	3C	2006	2008	18" Wheels	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Passat	3C	2006	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Phaeton	VW611	2003	2006	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Volkswagen	Phaeton	VW611	2003	2006	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Volkswagen	Rabbit	MK5;M5;1K	2006	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Rabbit	MK6;M6;5K	2008	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Routan		2009	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Volkswagen	Tiguan	VW316	2008	2011		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-115	6-201
Volkswagen	Touareg	7L	2004	2007		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Volkswagen	Touareg	7P	2008	2009		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	Touareg	7P	2010	2010		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-110	6-220B
Volkswagen	Touareg	7P	2011	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240
Volkswagen	Touareg	CR	2015	2021		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-109	6-240

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Volvo	C30	Y279	2007	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	C70	Y281	2006	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	S40	Y276	2004	2007	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-129	6-201
Volvo	S40	Y276	2008	2012		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	S60	Y283	2004	2008		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Volvo	S60	Y283	2009	2009		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Volvo	S60	Y283	2011	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	S60	V431	2015	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	S80	Y286	2004	2006		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Volvo	S80	Y286	2007	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	S80	Y286	2012	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	S80		2015	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	S80		2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Volvo	V50	Y280	2005	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	V60	Y352	2014	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	V60	Y352	2015	2017		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	V60		2018	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Volvo	V70	Y285	2004	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Volvo	V70	Y285	2008	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	V90		2017	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
Volvo	XC60	Y413	2009	2010		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Volvo	XC60	Y413	2010	2013		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	XC60	Y413	2014	2014		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	XC60	Y413	2015	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	XC70	Y381	2004	2007		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Volvo	XC70	Y381	2008	2011		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	XC70	Y381	2012	2015		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	XC70	Y381	2016	2018		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-138	6-231C
Volvo	XC90	Y289	2004	2004		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207

Make	Model	Vehicle_code	Year From	Year To	Qualifier	Frequency	U-Pro	PREMA Rubber Snap-in Valve	PREMA Metal/Graphite Clamp-in Valve	OE Service Kit	OE Service Valve
Volvo	XC90	Y289	2005	2010	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-122	
Volvo	XC90	Y289	2008	2014	433Mhz	433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH	6-139	6-231C
Volvo	XC90	Y289	2011	2014	315Mhz	315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Volvo	XC90	V526	2016	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-210H
VPG	MV-1		2012	2016		315 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207
Winnebago	Roam		2022	2022		433 MHz	PREM-NFC/PREM-ONE	6-207 / 6-207A-1/6-213B	6-266B/6-266B-BK 6-266A-SH		6-207